



Description	Non-control shift valve	Max. Pressure	NO
Position	NO	Service Life	NO
Fluids	NO	Port thread	M12X1.75
Operating Temp.	-40°C-80°C	Function	Used for the gas circuit control in gearbox,
Pressure	NO		